


6 DP PROVE OUT


ATTACHMENT-I



DP

1143

AREA MARKED AS X1 AND X2 NEED TO BE SHOT PEENED



ATTACHMENT-III

AFTSHAFT

AREA MARKED X1 AND X2 NEED TO BE SHOTPEENED

