

PRICE BID ANNEXURE- I

**WORK: "AMC FOR SELECTED AC PLANTS & PACKAGE UNITS, WINDOW & SPLIT AC UNITS,
OIL CHILLERS & PANEL ACS, REFREGERATORS AND EVAPORATIVE COOLING SYSTEMS"
TENDER NO: M&S/P&C/2010/019**

Sl.No	BHEL Cardex Number	MAKE	LOCATION	Year of Purch.	Capacity in TR	Unit rate Rs./TR /year	Total cost per year, Rs.
I	<u>CENTRAL PLANTS</u>						
1	CP -27	Voltas-5H40	29 Building Mechanical lab.	2000	40		
2	CP -10	Voltas-5H40	06 - Central Archieves	1984	40		
3	CP -26	Voltas-5H40	01-Sip oil chilling	1999	40		
4	CP -24	Voltas-5H40	06-Kolb oil chilling	1995	40		
5	CP -25	Kirloskar -F4	Oxygen Chilling plant	1998	10		
6	CP -17	Bitzer 111	01 Comp.Testing CO2 bulk plant	1989	1.5		
7	CP -29to32	Batliboi	9FA Block	2009	160		
		10 units	SUB- TOTAL IN RUPEES		331.5	T/R	
II	<u>PACKAGE AIR CONDITIONERS</u>						
Sl.No	BHEL Cardex Number	MAKE	LOCATION	Year of Purch.	Capacity in TR	Unit rate Rs./TR /year	Total cost per year, Rs.
1	PKG - 40	Botlibai	06-kolb Control Room with 6D48	1995	7.5		
2	PKG - 12,56,57	Carrier,Bluestar	07 Jig boaring machine center	1999	25		
3	PKG - 52	Blue star	02 (EM) Engg. PC room	1997	20		
4	PKG - 48,49	Blue star	6 MW diesel power house	1997	20		
5	PKG - 30,31	IBP	01 - SpinTest chilling unit	1991	22.5		
6	PKG - 55	Voltas	30TR Boiler control room	1999	15		
7	PKG - 29	Voltas	20TR Boiler control room	1989	7.5		
8	PKG-106 to110	Carrier	Admn.Bldg. 4th floor	2008	85		
9	PKG-111 to113	Carrier	Project - Civil office	2009	51		
10	PKG-114 to123	Carrier	Admn.Bldg (wages & finance)	2009	170		
11	PKG-124 to127	Carrier	IT Bldg Data processing center	2009	68		
		35 Units	SUB- TOTAL IN RUPEES		491.5		
III	<u>CASSATE AIR CONDITIONER</u>						
Sl.No	BHEL Cardex Number	MAKE	LOCATION	Year of Purch.	Capacity in TR	Unit rate Rs./TR /year	Total cost per year, Rs.
1	CAC-4	Diakin	Admn.Bldg. Entrance Reception	2007	2.0		
2	CAC-5	Diakin	Admn.Bldg. Entrance Reception	2007	2.0		
3	CAC-6	Diakin	Admn.Bldg. Entrance Reception	2008	2.0		
4	CAC-7	Diakin	Admn.Bldg. Entrance Reception	2009	2.0		
5	CAC-8	Diakin	Admn.Bldg. 4th floor Mini Conference Hall	2008	2.0		
6	CAC-9	Diakin	Admn.Bldg. 4th floor Main Conference Hall	2008	2.0		
7	CAC-10	Diakin	Admn.Bldg. 4th floor Main Conference Hall	2008	2.0		
8	CAC-11	Diakin	Factory Civil Projects Conferrance Hall	2009	2.0		
9	CAC-12	Diakin	Factory Civil Projects Conferrance Hall	2009	2.0		

10	CAC-13	Diakin	Adm.1st floor Finance AGM	2009	2.0		
11	CAC-14	Diakin	Adm.1st floor Finance Conferrance Hall AGM	2009	2.0		
12	CAC-15	Diakin	Adm.1st floor Finance Conferrance Hall	2009	2.0		
13	CAC-16	Diakin	Adm.1st floor Finance Conferrance Hall	2009	2.0		
14	CAC-17	Diakin	I.T. Building Coferrance Hall	2009	2.0		
15	CAC-18	Diakin	I.T. Building Coferrance Hall	2009	2.0		
16	CAC-19	Diakin	I.T. Building Coferrance Hall	2009	2.0		
17	CAC-20	Blue Star	02 Block - 6 Axis Machining center	2009	4.0		
18	CAC-21	Blue Star	02 Block - 6 Axis Machining center	2009	4.0		
19	CAC-22	Blue Star	02 Block - 6 Axis Machining center	2009	4.0		
20	CAC-23	Blue Star	02 Block - 6 Axis Machining center	2009	4.0		
21	CAC-24	Blue Star	02 Block - 6 Axis Machining center	2009	4.0		
		21 units	SUB- TOTAL IN RUPEES		52.0	T/R	
IV	SPLIT AIR CONDITIONERS						
Sl.No	BHEL Cardex Number	MAKE	LOCATION	Year of Purch.	Capacity in TR	Unit rate Rs./TR /year	Total cost per year, Rs.
1	SAC-52	Blue Star	Engg.Building, 2 nd Fl., P.C.Room	1997	3.0		
2	SAC-53	Blue Star	Engg.Building, 2 nd Fl., P.C.Room	1997	3.0		
3	SAC-100	Videocon	Gen.Hospital, OPD, Mini Operation Theatre	2004	1.5		
4	SAC-107	LG	90 Bldg.Instrumentation lab AC section	2006	1.5		
5	SAC-112	LG	ED's Bungalow, BHEL T/S	2004	1.5		
6	SAC-113	LG	ED's Bungalow, BHEL T/S	2004	1.5		
7	SAC-138	LG	ED's Bungalow, BHEL T/S	2006	1.5		
8	SAC-139	LG	ED's Bungalow, BHEL T/S	2006	1.5		
9	SAC-140	LG	ED's Bungalow, BHEL T/S	2006	1.5		
10	SAC-141	LG	ED's Bungalow, BHEL T/S	2006	1.5		
11	SAC-129	LG	Q.no.459 Type-VI BHEL T/S ED-MrKrishnan	2006	1.5		
12	SAC-135	LG	ED residence BHEL T/S AC section	2006	1.5		
13	SAC-153	LG	ED residence BHEL T/S AC section	2006	1.5		
14	SAC-156	LG	ED-Residence, BHEL Township, Hyd-32	2006	1.5		
15	SAC-163	LG	BHEL Township, ED's Quarter	2001	1.5		
16	SAC-272	Voltas	Q.no.459 Type-VI BHEL T/S -MrKrishnan	2009	1.5		
17	SAC-273	Voltas	Q.no.459 Type-VI BHEL T/S E.D -MrKrishnan	2009	1.5		
18	SAC-274	Voltas	Q.no.459 Type-VI BHEL T/S E.D.MrKrishnan	2009	1.5		
19	SAC-121	LG	Adm.Bldg. 2nd Fl., GM. Aravindh Gupta	2006	1.5		
20	SAC-122	LG	Adm.Bldg. 2nd Fl., GM. Aravindh Gupta	2006	1.5		
21	SAC-127	LG	01 Block, Adhitya Conf. Hall, E/Side	2006	1.5		
22	SAC-128	LG	01 Block, Adhitya Conf. Hall, E/Side	2006	1.5		
23	SAC-132	LG	Residence, BHELT/S, Qtr:2516-A	2006	1.5		
24	SAC-133	LG	GM – R.K.Wanchoo Residence HIG, Phase-II, No-22 , Madinaguda	2006	1.5		
25	SAC-136	LG	GM- T.Raghunadha Reddy Residence, BHEL T/S	2006	1.5		
26	SAC-137	LG	GM – P.R.Shriram Residence,186/D, BHEL Township, Vacated Quarter, under T/S Adm.	2006	1.5		
27	SAC-143	LG	02 Annexe,1 st Fl., Server Room	2006	1.5		
28	SAC-145	LG	Admn.Bldg., 1 st Floor, Finance Conference Hall	2006	1.5		
29	SAC-146	LG	Admn.Bldg., 1 st Floor, Finance Conference Hall	2006	1.5		
30	SAC-147	LG	Admn.Bldg., 1 st Floor, Finance Conference Hall	2006	1.5		
31	SAC-148	LG	Admn.Bldg., 1 st Floor, Finance Conference Hall	2006	1.5		
32	SAC-149	LG	EDP.Bldg., 1 st Fl.GM-Finance Cabin, N.N.Dawnn	2006	1.5		
33	SAC-150	LG	EDP.Bldg., 1 st Fl.GM-Finance Cabin, N.N.Dawnn	2006	1.5		
34	SAC-151	LG	Admn.Bldg., Gr. Fl., HR AGM-Victor	2006	1.5		

35	SAC-152	LG	Admn.Bldg., Gr. Fl., HR AGM-Victor	2006	1.5		
36	SAC-155	LG	GM- Subba Rao Res: Qtr. No: 461, BHEL T/S	2006	1.5		
37	SAC-158	LG	01 Annexe, 1 st Fl., GM-P.Palguna Rao	2006	1.5		
38	SAC-159	LG	01 Annexe, 1 st Fl., GM-P.Palguna Rao	2006	1.5		
39	SAC-160	LG	HRDC Room no:101	2006	1.5		
40	SAC-161	LG	HRDC Room no:101	2006	1.5		
41	SAC-162	LG	HRDC Room no:101	2006	1.5		
42	SAC-165	LG	01 Annexe, Gr. Floor, AGM -	2007	1.5		
43	SAC-166	LG	01 Annexe, Gr. Floor, AGM -	2007	1.5		
44	SAC-179	LG	Admn. 1st floor Adj.Chairman Room	2007	1.5		
45	SAC-182	LG	GM-F.A.Khan- Res: HIG-153, BHEL Town ship	2007	1.5		
46	SAC-183	LG	Admn. 1st floor Adj.Chairman Room	2007	1.5		
47	SAC-184	LG	GM-Mr.Srivathasava-, Admn.Bldg., 1 st Fl.	2007	1.5		
48	SAC-185	LG	GM-Mr.Srivathasava-, Admn.Bldg., 1 st Fl.	2007	1.5		
49	SAC-186	LG	Gen.Hospital, Special Room No-4	2007	1.5		
50	SAC-187	LG	Gen.Hospital, Special Room No-3	2007	1.5		
51	SAC-188	LG	Admn Bldg 1st floor adj to CMD room	2007	1.5		
52	SAC-189	LG	GM-Aravind Gupta Res: HIG-452, Phase-1, BHEL	2007	1.5		
53	SAC-190	LG	GM-V.Sree Venkateswarlu Res: Qtr.No:451, BHEL T/S,	2007	1.5		
54	SAC-66	LG	90 Bldg.Instrumentation labAC section	2001	1.5		
55	SAC-208	Videocon	GM Srivasthava Residence HIG - 405 BHEL T/S	2008	1.5		
56	SAC-82	Voltas	90 Building, 1 st Fl., Lab	2003	1.5		
57	SAC-83	Voltas	90 Building, 1 st Fl., Lab	2003	1.5		
58	SAC-84	Voltas	90 Building, 1 st Fl., Lab	2003	1.5		
59	SAC-85	Voltas	90 Building, 1 st Fl., Lab	2003	1.5		
60	SAC-86	Voltas	90 Building,, Gr.Fl, Lab,	2003	1.5		
61	SAC-91	Videocon	HRDC, 1 st Fl. Room-118	2004	1.5		
62	SAC-92	Videocon	HRDC, 1 st Fl. Room-118	2004	1.5		
63	SAC-93	Videocon	HRDC, 1 st Fl. Room-118	2004	1.5		
64	SAC-94	Videocon	HRDC, 1 st Fl. Room-118	2004	1.5		
65	SAC-95	Videocon	HRDC, 1 st Fl. Room-118	2004	1.5		
66	SAC-96	Videocon	HRDC, 1 st Fl. Room-118	2004	1.5		
67	SAC-97	Videocon	Gen.Hospital, OPD Emergency Ward	2004	1.5		
68	SAC-98	Videocon	Gen.Hospital, OPD Emergency Ward	2004	1.5		
69	SAC-99	Videocon	Gen.Hospital, OPD Emergency Ward	2004	1.5		
70	SAC-203	LG	03 Block, Switch Gear Testing area	2008	2.0		
71	SAC-204	LG	03 Block, Switch Gear Testing area	2008	2.0		
72	SAC-205	LG	03 Block, Switch Gear Testing area	2008	2.0		
73	SAC-206	LG	03 Block, Switch Gear Testing area	2008	2.0		
74	SAC-207	LG	03 Block, Switch Gear Testing area	2008	1.5		
75	SAC-214	Videocon	Admn.Bldg., Gr.Fl.,AGM- Adi Seshu	2008	1.5		
76	SAC-221	Videocon	Gen.Hospital, Special Room No-1	2008	1.5		
77	SAC-222	Videocon	Gen.Hospital, Special Room No-2	2008	1.5		
78	SAC-223	Videocon	Gen.Hospital, Special Room No-5	2008	1.5		
79	SAC-224	Videocon	Gen.Hospital, Special Room No-6	2008	1.5		
80	SAC-225	Videocon	Gen.Hospital, Special Room No-7	2008	1.5		
81	SAC-226	Videocon	Gen.Hospital, Special Room No-8	2008	1.5		
82	SAC-227	Videocon	Gen.Hospital, Special Room No-9	2008	1.5		
83	SAC-228	Videocon	Gen.Hospital, Mini Conference Hall	2008	1.5		
84	SAC-229	Videocon	Gen.Hospital, Mini Conference Hall	2008	1.5		
85	SAC-230	Videocon	Gen.Hospital, M.S.Office (superindent)	2008	1.5		

86	SAC-231	Videocon	GM-P.Phalguna Rao Res:HIG-427-A, Phase-1,BHEL,Hyd-32	2008	1.5		
87	SAC-265	Voltas	Disaster Recovery cente nearTICbldg	2009	1.5		
88	SAC-266	Voltas	Disaster Recovery cente nearTICbldg	2009	1.5		
89	SAC-267	Voltas	Disaster Recovery cente nearTICbldg	2009	1.5		
90	SAC-268	Voltas	Disaster Recovery cente nearTICbldg	2009	1.5		
91	SAC-269	Voltas	Disaster Recovery cente nearTICbldg	2009	1.5		
92	SAC-270	Voltas	Disaster Recovery cente nearTICbldg	2009	1.5		
93	SAC-271	Voltas	79 Bldg. NTPC office	2009	1.5		
94	SAC-275	Blue Star	9 FA Control Room	2008	1.5		
95	SAC-276	Blue Star	9 FA Control Room	2008	1.5		
96	SAC-277	Blue Star	9 FA Testing Control Room 1st floor	2008	1.5		
97	SAC-278	Blue Star	9FA Testing Control Room 1st floor	2008	1.5		
98	SAC-279	Blue Star	9FA Testing Control Room 1st floor	2008	1.5		
99	SAC-280	Blue Star	01 Cross Bay S.T.Testing control Panel room (New)	2008	1.5		
100	SAC-281	Blue Star	01 Cross Bay S.T.Testing control panel room (New)	2008	1.5		
101	SAC-282	Blue Star	01 Cross Bay S.T.Testing control room (New) office room	2008	1.5		
102	SAC-283	Blue Star	01 Cross Bay S.T.Testing control room (New) office room	2008	1.5		
103	SAC-284	Blue Star	01 Cross Bay S.T.Testing control room (New) office room	2008	1.5		
104	SAC-285	Blue Star	01 Cross Bay S.T.Testing control room (New) Conference Hall	2008	1.5		
105	SAC-286	Blue Star	01 Cross Bay S.T.Testing control room (New) Conference Hall	2008	1.5		
106	SAC-287	Blue Star	01 Cross Bay S.T.Testing control room (New)	2008	1.5		
107	SAC-288	Blue Star	01 Cross Bay S.T.Testing control room (New)	2008	1.5		
108	SAC-289	Blue Star	01 Cross Bay S.T.Testing control room (New)	2008	1.5		
109	SAC-290	Blue Star	01 Cross Bay S.T.Testing control room (New) Staff room	2008	1.5		
110	SAC-291	Blue Star	01 Cross Bay S.T.Testing control room (New) Staff room	2008	1.5		
111	SAC-292	Carrier	Admn. Bldg. 4th Floor G.M - V.S.Vekateshwarulu	2008	1.5		
112	SAC-293	Carrier	Admn. Bldg. 4th Floor G.M - V.S.Vekateshwarulu	2008	1.5		
113	SAC-294	Carrier	Admn. Bldg. 4th Floor A.G.M - G.S.Ashok Kumar	2008	1.5		
114	SAC-295	Carrier	Admn. Bldg. 4th Floor A.G.M - Mannan	2008	1.5		
115	SAC-296	Carrier	Admn. Bldg. 4th Floor AGM - S.M.Kalkar	2008	1.5		
116	SAC-297	Carrier	Admn. Bldg. 4th Floor Server Room	2008	1.5		
117	SAC-298	Carrier	Admn. Bldg. 4th Floor Server Room	2008	1.5		
118	SAC-299	Carrier	Admn. Bldg. 4th Floor A.G.M - T.Sammaiah	2008	1.5		
119	SAC-300	Carrier	Admn. Bldg. 4th Floor A.G.M - M.N.Koteshwar Rao	2008	1.5		
120	SAC-301	Carrier	Admn. Bldg. 4th Floor A.G.M - M.N.Koteshwar Rao	2008	1.5		
121	SAC-302	Carrier	Admn. Bldg. 4th Floor A.G.M - B.Murali Mohan	2008	1.5		
122	SAC-303	Carrier	Factory Civil Projects AGM P.J.Reddy	2009	1.5		
123	SAC-304	Carrier	Admn.Bldg Finance Mini Conferrance Hall	2009	1.5		
124	SAC-305	Carrier	I.T. Building P.C.Room office	2009	1.5		
125	SAC-306	Carrier	I.T. Building P.C.Room office	2009	1.5		
126	SAC-307	Carrier	I.T.Building Sr.DGM. S.Koteshwar Rao	2009	1.5		
127	SAC-308	Carrier	I.T.Building Sr.DGM. C.Suresh Kumar	2009	1.5		
128	SAC-309	Carrier	I.T. Building AGM - P.Narayana	2009	1.5		
129	SAC-310	Carrier	I.T.Building GM - F.A.Khan	2009	1.5		
130	SAC-311	Carrier	I.T.Building GM - F.A.Khan	2009	1.5		

		130 Units			200.00		
V	WINDOW AIR CONDITIONERS						
Sl.No	BHEL Cardex Number	MAKE	LOCATION	Year of Purch.	Capacity in TR	Unit rate Rs./TR /year	Total cost per year, Rs.
1	370	Lancer	Admn.Bldg.,Gr Floor .-GM- A.Victor Office Room	1978	1.5		
2	532	Voltas	Adm.Bldg.,Gr.Fl-Sub Contract	1986	1.5		
3	637	Lancer	Admn.bldg. Gr. Floor . DGM (HR)- Arun paul	1991	1.5		
4	8(N)	LG	Admn. Bldg. Gr.Floor , SR.DGM-Shaji Vargees	2004	1.5		
5	718	Avalanche	Adm.Bldg. Gr.Floor - Conferene Hall	1994	1.5		
6	784	Avalanche	Adm.Bldg. Gr.Floor .- Conferene Hall	1999	1.5		
7	36(N)	LG	Adm.Bldg., Gr.,Floor .-Sr.DGM-D.Vidyasagar	2004	1.5		
8	41(N)	LG	Admn.Bldg. Gr.Floor Sr.DGM-B.Shankeraiah	2004	1.5		
9	75(N)	LG	Admn.Build., Gr Floor	2005	1.5		
10	111(N)	LG	Admn. Bldg. Gr.Floor , AGM-B.Phanindra Kumar	2006	1.5		
11	139(N)	LG	Adm, Gr.Fl.,Sr.DGM-Gopinath Rao	2007	1.5		
12	45(N)	LG	Admn.Bldg., 1st Fl. -Inv Plg.AGM-T.Subhash	2004	1.5		
13	106(N)	LG	Admn.Bldg., 1st Floor -Inv Plng.AGM-T.Subhash	2006	1.5		
14	83(N)	LG	Admn.Bldg.,1st Fl.,AGM-Panchadhar, Vigilece Dept.	2005	1.5		
15	168	National	Admn.Bldg., 2ndFloor .,AGM- PVR Prasad	1967	1.5		
16	42(N)	LG	Adm.Bldg., 2nd Fl.-AGM-PVR Prasad	2004	1.5		
17	214	Lancer	Adm Bldg.2nd Fl.,Sr.DGM-UmaMaheswara Rao	1967	1.5		
18	24(N)	LG	Adm.Bldg., 2nd Fl.-GM-Madhu Soodan Rao	2004	1.5		
19	13(N)	LG	Admn.Bldg., 2nd Fl.,AGM- K.E.P.Kumar	2004	1.5		
20	67(N)	LG	Admn.Build., 2nd Floor AGM-B.D.Pandey	2005	1.5		
21	78(N)	LG	Admn.Bldg., 2ndFloor AGM- P.Rama Kuchel	2005	1.5		
22	80(N)	LG	Admn.Build., 2nd Floor Engg & Tendering Dept.	2005	1.5		
23	86(N)	LG	Admn.Build., 2nd Floor AGM-Prabhaker Rao	2005	1.5		
24	92(N)	LG	Admn.Build., 2nd Floor Engg & Tendering Dept.	2005	1.5		
25	98(N)	LG	Admn.Bldg., 2nd Floor AGM- K.Maisaiah	2005	1.5		
26	304	National	Admn Build. 5th Floor Lift Room	1974	1.5		
27	685	Lancer	Admn Build. 5th Floor Lift Room	1994	1.5		
28	473	Voltas	Tel. Exchange, Switch Room	1985	1.5		
29	559	Voltas	Tel.Exchange-Telex Room	1987	1.5		
30	113(N)	LG	Tel. Exchange, E.D. Conference Room	2006	1.5		
31	133(N)	LG	Tel.Exchange-AGM-S.Srikanth	2007	1.5		
32	479	Voltas	EDP Bldg., Strong Room	1985	1.5		
33	749	Avanlanche	EDP Bldg., Strong Room	1998	1.5		
34	755	Avanlanche	EDP Bldg., Strong Room	1998	1.5		
35	355	Voltas	Engg.Bldg., Gr.Fl., Server Room - Cabin -044	1994	1.5		
36	51(N)	LG	Engg.Bldg., Gr.Fl., Server Room - cabin -009	2004	1.5		
37	478	Voltas	Engg.Build., 1stFloor Server Room	1985	1.5		
38	499	Voltas	Engg.Build., 1st Fl.-Server Room	1985	1.5		
39	431	Voltas	Engg.Bldg., 1st.Floor AGM-Sandeep Narang	1983	1.5		
40	526	Voltas	Engg.Bldg., 2nd Floor PC Room	1982	1.5		
41	469	Voltas	Engg.Bldg., 2nd Floor AGM-CNV Ramana	1985	1.5		
42	552	Voltas	Engg.Bldg., 2nd Floor PC Room	1986	1.5		
43	798	Avalanche	01 Annex, Gr.Floor AGM-KVP Rao	1999	1.5		

44	61(N)	LG	01 Annex, Gr.Fl., AGM-KVP Rao	2005	1.5		
45	12(N)	LG	01 Annex, Gr.Fl., Sr.DGM-E.Pandarinath	2004	1.5		
46	88(N)	LG	01 Annexe, Gr.Fl.,AGM-Desh Pande	2005	1.5		
47	129(N)	LG	01 Annexe, Gr. Fl.,AGM-R.Sreedharan	2007	1.5		
48	155(N)	Samsung	01Annex, TC & GT Conf.Hall E/side	2008	1.5		
49	156(N)	Samsung	01Annex, TC & GT Conf.Hall E/side	2008	1.5		
50	768	Avalanche	01 Annex,1st Fl.,Server Room	1998	1.5		
51	9(N)	LG	01 Annex 1st.Fl., Sr.DGM-Reddyeswar	2004	1.5		
52	10(N)	LG	01 Annex, 1st Fl., AGM- T.M.Rao	2004	1.5		
53	52(N)	LG	01 Annex, 1 st Fl. -Sr.DGM-K.Rajeswara Rao	2004	1.5		
54	65(N)	LG	01 Annexe, 1st Fl., AGM-G.Uday Kumar	2005	1.5		
55	117(N)	LG	01 Annex,1st Fl., AGM- A.B.Ravi Chandran	2006	1.5		
56	144	National	01 Annexe,2nd Fl., AGM-R.Srinivasan	1966	1.5		
57	7(N)	LG	01 Annex 2nd .Fl., Sr.DGM-B.Srinivas	2004	1.5		
58	110(N)	LG	01 Annex,2nd Fl., AGM- V.C.Krishnan	2006	1.5		
59	97	Lancer	01 Block, Compressor Testing Lab	1966	1.5		
60	451	Voltas	01 Block,Glass Cabin, M&S Electronics Cabin	1984	1.5		
61	632	Voltas	01 Block,Glass Cabin, M&S Electronics Cabin	1989	1.5		
62	777	Avalanche	01 Block,Glass Cabin, M&S Electronics Cabin	1996	1.5		
63	576	Arco	01 Block,3D 3M QC	1989	1.5		
64	199	Lancer	01 Block, Compressor Testing Lab	1967	1.5		
65	365	Lancer	01 Block,3D 3M QC	1978	1.5		
66	747	Avalanche	01 Block-Time Office	1998	1.5		
67	697	Avalanche	01 Block Quality Control Cabin	1996	1.5		
68	776	Avalanche	01 Block Quality Control Cabin	1998	1.5		
69	14(N)	LG	01 Block, Sr.DGM-S.Bhasker Rao	2004	1.5		
70	32(N)	LG	01 Block, Compr.Testing, Sr.DGM-MK.Ghosh	2004	1.5		
71	43(N)	LG	01 Block,Cross Bay-Sr.DGM-Shanker	2004	1.5		
72	635	Lancer	01 Block Quality Control Cabin	2005	1.5		
73	101(N)	Videocon	01 Block, Tool Sharpening, (under 5 Axis)	2005	1.5		
74	102(N)	Videocon	01 Block, Tool Sharpening, (under 5 Axis)	2005	1.5		
75	103(N)	Videocon	01 Block, Tool Sharpening, (under 5 Axis)	2005	1.5		
76	104(N)	Videocon	01 Block, Tool Sharpening, (under 5 Axis)	2005	1.5		
77	121(N)	LG	01 Block, Sr.DGM-Isrual Raju	2006	1.5		
78	91(N)	LG	01 Block, GT Control Room	2005	1.5		
79	132	Lancer	02 Annex, Gr.Fl.-AGM- R.Acharya	1966	1.5		
80	259	National	02 Annex Gr.Fl. SR.DGM-Devesh Raj	1968	1.5		
81	526	Voltas	02 Annexe, Gr.Fl., M&S P.C.Room	1986	1.5		
82	698	Avalanche	02 Annexe, Gr.Fl., Q.C, Conference Hall	1994	1.5		
83	766	Avalanche	02 Annexe, Gr.Fl. Time Office	1998	1.5		
84	772	Avalanche	02 Annexe, Gr.Fl., Q.C. Conference Hall	1998	1.5		
85	774	National	02 Annexe, Gr.Fl., M&S P.C.Room	1998	1.5		
86	783	National	02 Annex,Gr.Fl.M&S PC Room	1999	1.5		
87	17(N)	LG	02 Annex Gr.Fl., AGM/ Ravindranathbabu	2004	1.5		
88	21(N)	LG	02 Annex Gr. Fl.,AGM-M.B.Dass	2004	1.5		
89	69(N)	LG	02 Annexe, Gr.Fl.Sr.DGM-K.Sudarshan Rao	2005	1.5		
90	53	Lancer	02 Annex,Gr.Fl, AGM- D.Vijaya Babu	2006	1.5		
91	863	LG	02 Annexe, Gr.Fl.-AGM-AGM-C.Suresh Kumar	2004	1.5		
92	135(N)	LG	02 Annexe, Gr.Fl.-KV Prasad DGM/M&S	2007	1.5		
93	136(N)	LG	02 Annexe, Gr.Fl.-DGM (EM)-Subramanyam	2007	1.5		
94	146(N)	Samsung	02 Annexe, Gr.Fl., M&S Conf.Hall	2008	1.5		
95	147(N)	Samsung	02 Annexe, Gr.Fl., M&S Conf.Hall	2008	1.5		

96	787	Avalanche	02 Annexe, 1st Fl.Server Room	1999	1.5		
97	1(N)	LG	02 Annexe, 1st Fl., Sr.DGM-K.K.Rai	2004	1.5		
98	11(N)	LG	02 Annex 1st. Fl., Sr.DGM-Vijaya Kumar	2004	1.5		
99	66(N)	LG	02 Annexe, 1st Fl., E&M Conf.Hall	2005	1.5		
100	68(N)	LG	02 Annexe, 1st Fl., Sr.DGM-cabin	2005	1.5		
101	81(N)	LG	02 Annexe,1st Fl.-cabin	2005	1.5		
102	118(N)	LG	02 Annexe, 1 st Fl.-DGM-Madhusudan Reddy/SK.Pandae	2006	1.5		
103	125(N)		02 Annex,1st Fl.,AGM-Veera Pratap	2006	1.5		
104	127(N)	LG	02 Annexe, 1st Fl., AGM- P.Ashok Varma	2006	1.5		
105	128(N)	LG	02 Annexe, 1st Fl.,AGM-U.Sreedhar	2007	1.5		
106	138(N)	LG	02 Annexe, 1st Fl., cabin	2007	1.5		
107	227	Lancer	02 Annex,2nd Fl.-GM-G.Vidya Sagar	1968	1.5		
108	477	Lancer	02 Annex,2nd Fl, GM-Vidya Sagar	1985	1.5		
109	728	Avalanche	02 Annex,2nd Fl, GM-Vidya Sagar - Office		1.5		
110	18(N)	LG	02 Annex 2nd. Fl., AGM- CH.Madhava Rao	2004	1.5		
111	20(N)	LG	02 Annex 2nd. Fl., AGM-D.C.Rao(FSS)	2004	1.5		
112	49(N)	LG	02 Annex, 2nd Fl., Sr.DGM-B.Raj Kumar	2004	1.5		
113	89(N)	LG	02 Annex 2nd. Fl., AGM- CH.Madhava Rao	2005	1.5		
114	105(N)	LG	02 Annex, 2nd Fl.- AGM- A.Kayarkar	2006	1.5		
115	489	Voltas	02 Block, Impregnation Plant Control Room	1985	1.5		
116	521	Voltas	02 Block, Impregnation Plant Control Room	1986	1.5		
117	616	Voltas	02 Block -High Voltage -Coil Winding Testing	1989	1.5		
118	620	Voltas	02 Block, Glass Cabin, Server Room	1989	1.5		
119	681	Avalanche	02 Block, Impregnation Plant Control Room	1994	1.5		
120	754	Avalanche	02 Block, Coil Shop, Hydraulic Press m/c	1998	1.5		
121	93(N)	LG	02 Blok, Sr.DGM-Ravindranath	2004	1.5		
122	123(N)	LG	02 Block ,E/S, Glass Cabin-Sr.DGM- Dass	2006	1.5		
123	70(N)	LG	03 Annexe, Gr.Fl.,Sr.DGM-V.Ravindranath	2005	1.5		
124	238	National	03 Annex, 1st Fl.-GM Office	1968	1.5		
125	744	Avalanche	03 Annex, 1st Fl-Sr.DGM-Pulla Reddy	1998	1.5		
126	116(N)	LG	03 Annexe, 1st Fl.,GM Office	2006	1.5		
127	140(N)	LG	03 Annexe, 1st Fl., Conferece Hall	2007	1.5		
128	141(N)	LG	03 Annexe, 1st Fl., Conferece Hall	2007	1.5		
129	335	National	03 Block, Measuring Centre	1975	1.5		
130	429	Voltas	03 Block, 3D Measuring Centre	1983	1.5		
131	475	Voltas	03 Block, 3D Measuring Centre	1985	1.5		
132	627	Voltas	03 Block, (63 Stores) Near Cycle Stand	1989	1.5		
133	655	Lancer	03 Block, SB CNC-HMT	1991	1.5		
134	706	Avalanche	03 Block, 26/28 Stores	1994	1.5		
135	116	National	03 Block, Vaccum Brazing Centre	1999	1.5		
136	23(N)	LG	04 Annex, AGM- P.Satya Narayana	2004	1.5		
137	87	National	04 Block, Express Lab	1966	1.5		
138	150	Lancer	04 Block, Express Lab	1967	1.5		
139	507	Voltas	04 Block, Express Lab	1986	1.5		
140	291	National	06 Annexe,Gr.Fl.Electronics Stores	1968	1.5		
141	398	Voltas	06 Annexe,Gr.Fl.Electronics Stores	1982	1.5		
142	563	Voltas	06 Annexe,Gr.Fl.Electronics Stores	1987	1.5		
143	773	Avalanche	06 Annexe,Gr.Fl.Electronics Stores	1998	1.5		
144	40(N)	LG	06 Annexe,1st Fl.-Sr.DGM-T.Ananda Rao	2004	1.5		
145	53(N)	LG	06 Annexe, Gr.Fl.-Amonia Print Room	2004	1.5		
146	71(N)	LG	06 Annexe, Gr.Fl.Amonia Print Room	2005	1.5		
147	25(N)	LG	06 Annex, 1st.Fl. GM-Achyuth Kumar	2004	1.5		

148	144(N)	Samsung	06 A0, Printing Press	2008	1.5		
149	107(N)	LG	06 Annexe, 1st Fl.-DGM-M.Mallaiah	2006	1.5		
150	320	Voltas	06 Annex, 1st Fl., Standards PC Room	1974	1.5		
151	230	National	06 Annex, 1st.Fl-PC Room.	1987	1.5		
152	399	Lancer	06 Block, NDT Centre-Dark room	1982	1.5		
153	509	Voltas	06 Block, Furnace Control Room	1986	1.5		
154	581	Voltas	06 Block, NDT-X ray dark room	1988	1.5		
155	596	Voltas	06 Block, Furnace Control Room	1988	1.5		
156	703	Avalanche	06 Block, Conferrance room	1994	1.5		
157	130(N)	LG	06 Block, AGM-S.Pallam Raju	2007	1.5		
158	753	Avalanche	07 Annex, Gr.Fl., P.C.Room	1998	1.5		
159	764	Avalanche	07 Annex, Gr.Fl., P.C.Room	1998	1.5		
160	803	Avalanche	07 Annex, Gr.Fl., P.C.Room	1999	1.5		
161	26(N)	LG	07 Annex, Gr. Fl.Sr.DGM-P.Venkateswara Rao	2004	1.5		
162	57(N)	LG	07 Annexe, Gr.Fl.-AGM-G.Papa Rao	2004	1.5		
163	185	Nititional	07 Annexe, 1st Fl.-P.C.Room	1967	1.5		
164	572	Voltas	07 Annex, 1st Floor, P.C.Room	1985	1.5		
165	530	Voltas	07 Annex, 1st Floor, P.C.Room	1986	1.5		
166	737	Avalanche	07 Annexe, 1 st Fl. PC Room	1996	1.5		
167	3(N)	LG	07 Annexe, 1 st Fl.AGM- Raj Kumar	2004	1.5		
168	56(N)	LG	07 Annexe, 1st Fl.- AGM Office	2004	1.5		
169	100(N)	LG	07 Annexe, 1st Fl.- AGM- Yugandhar	2005	1.5		
170	219	Lancer	07 Annexe, 2nd Fl.AGM-CSR Murthy	1966	1.5		
171	4(N)	LG	07 Annexe, 2nd Fl.AGM-CSR Murthy	2004	1.5		
172	269	Lancer	07 Annexe, 2nd Fl., Conf.Hall	1994	1.5		
173	Loan unit	Lancer	07 Annexe, 2nd Fl., Conf.Hall		1.5		
174	782	Avalanche	07 Annex, 2nd Fl., P.C.Room	1999	1.5		
175	774	Avalanche	07 Annex, 2nd Floor, P.C.Room	1999	1.5		
176	791	Avalanche	07 Annex, 2nd Floor, P.C.Room	1999	1.5		
177	792	Avalanche	07 Annex, 2nd Floor, P.C.Room	1999	1.5		
178	115(N)	LG	07 Annexe, 2nd Fl.- Sivarama Krishna	2006	1.5		
179	164	Voltas	07-Tool Room, K-Centre	1967	1.5		
180	346	Voltas	07-Tool Room, Quality Control	1976	1.5		
181	378	Voltas	07 Tool Room- Optical Grinding Machine	1978	1.5		
182	383	Voltas	07 Tool Room, wire cutting m/c	1982	1.5		
183	394	Voltas	07 Tool Room, wire cutting m/c	1982	1.5		
184	408	Voltas	07 Tool Room- Optical Grinding Machine	1982	1.5		
185	423	Voltas	07 Tool Room, Thread Grinding machine	1983	1.5		
186	645	Keysons	07 Tool Room, Thread Grinding m/c	1991	1.5		
187	414	Voltas	08 Block,Common Work Shop,Glass Cabin	1982	1.5		
188	158	Lancer	10-Repair Shop, Gauge Room	1967	1.5		
189	733	Avalanche	10-Repair Shop,Bay-1, HMT-CNC m/c	1996	1.5		
190	536	Voltas	11 Block, TC>, 01 Stores	1986	1.5		
191	417	Voltas	11 Block, TC>, 01 Stores	1982	1.5		
192	671	Lancer	11 Block, PC Room	1991	1.5		
193	549	Voltas	29 Build. 1 st Fl., Chemical Store	1986	1.5		
194	142(N)	Samsung	29 Building , 1st Fl.-Lab	2008	1.5		
195	143(N)	Samsung	29 Building , 1st Fl.-Lab	2008	1.5		
196	29(N)	LG	36/11,Gr.Fl., Sr.DGM-A.K.Jha	2004	1.5		
197	132(N)	LG	36/11, Gr. Fl., AGM- VLM.Sharma	2007	1.5		
198	562	Voltas	36/11 Build,1st Fl-Server Room	1987	1.5		
199	643	Lancer	36/11 Build,1st Fl-Server Room	1994	1.5		
200	27(N)	LG	36/11, 1 st .Fl.,AGM-BK.Nair	2004	1.5		

201	134(N)	LG	36/11, 1st Fl., Sr.DGM-KSS Prasad	2007	1.5		
202	82(N)	LG	36/11,1st Fl.,DGM-Y.Sivarama Krishna	2005	1.5		
203	28(N)	LG	36/11, 2 nd .Fl., Conference Hall	2004	1.5		
204	63(N)	LG	36/11, 2nd Fl.- AGM-CV.Shambu Prasad	2005	1.5		
205	657	Lancer	51 Block VDF Computer Room	1983	1.5		
206	673	Lancer	51 Block, Glass Cabin,VDF Room	1991	1.5		
207	330	Lancer	51 Block,VDF CNC Cabin	2005	1.5		
208	465	Voltas	70 building, Calibrating Room	1985	1.5		
209	525	Lancer	70 Bldg., Pump Testing Control Room	1986	1.5		
210	541	Lancer	70 Bldg., Pump Testing Control Room	1986	1.5		
211	542	Voltas	70 Bldg., Calibrating Room	1986	1.5		
212	565	Voltas	70 Building, Guest Room	1987	1.5		
213	576	Lancer	70 Bldg., Pump Testing Control Room	1987	1.5		
214	626	Voltas	70 Building, Calibrating Room	1989	1.5		
215	389	Voltas	70 Bldg., Pump Testing Control Room	1982	1.5		
216	600	Voltas	70 Bldg., Pump Testing Control Room	1988	1.5		
217	660	Lancer	70 Building, P.C.Room	1991	1.5		
218	675	Lancer	70 Build., Testig Control Room	1991	1.5		
219	31(N)	LG	70 Building, Sr.DGM-P.Srinivas Rao	2004	1.5		
220	108(N)	LG	70.Bldg., AGM - Sri Vasthava	2006	1.5		
221	131(N)	LG	70 Bldg., Sr.DGM-P.Bapu Reddy,Q.C	2007	1.5		
222	564	Voltas	71 Build, Balancing Tunnel Old Control Room	1987	1.5		
223	568	Voltas	71 Build,1st Fl., Balanc. Tunnel Guest Room	1987	1.5		
224	351	Voltas	71 Build, Balanc.Tunnel Old Control Room	1977	1.5		
225	372	Voltas	71 Build, Balanc.Tunnel Old Control Room	1978	1.5		
226	416	Voltas	71 Build, Balanc.Tunnel Old Control Room	1982	1.5		
227	668	Lancer	71 Build,1st Fl., Balanc.Tunnel Guest Room	1991	1.5		
228	34(N)	LG	86 Build.1 st Fl., DGM-S.Jaya Sunder Rao	2004	1.5		
229	35(N)	LG	86 Build.1 st Fl., DGM-C.Vasudev	2004	1.5		
230	87(N)	LG	86 Build.,1st Fl.,AGM-B.G.Gadhave	2005	1.5		
231	700	Avalanche	90 Build. 1st Fl., Instrumentation	1994	1.5		
232	746	Avalanche	90 Build. 1st Fl., Instrumentation	1998	1.5		
233	781	Avalanche	90 Build. 1st Fl., Instrumentation	1999	1.5		
234	743	Avalanche	90 Build. 1st Fl., Carmas Room	1996	1.5		
235	182	Lancer	RUY Annex, Gr.Fl., Conference Hall	1967	1.5		
236	410	Voltas	RUY Annex, Gr.Fl., Conference Hall	1982	1.5		
237	730	Avlanche	RUY Annex,Gr.Fl, DGM-Krishnan	1996	1.5		
238	38(N)	LG	RUY Annex,Gr.Fl.Sr.DGM-Shankeran	2004	1.5		
239	55(N)	LG	RUY Annex, 1st Fl., Sr.DGM-P.Madhu Babu	2004	1.5		
240	90(N)	LG	RUY Annex,Gr.Fl.-AGM-Devi Prasanna Kumar	2005	1.5		
241	119(N)	LG	RUY Annex, 1 st Fl., AGM- G.Jagdeep	2006	1.5		
242	30(N)	LG	RUY Annex, 1 st Fl., AGM- G.Jagdeep	2004	1.5		
243	421	Voltas	TIC Build., Library P.C.Room	1983	1.5		
244	487	Voltas	TIC Bldg., (Pulv)-PC Room	1985	1.5		
245	639	Keyson	TIC Build., Library P.C.Room	1991	1.5		
246	60(N)	LG	TIC Bldg., AGM (Pulv)-Kulakarni	2004	1.5		
247	NN		CISF Factory Main Gate, CISF Control Room	1967	1.5		
248	419	Voltas	CISF Factory Main Gate, CISF Control Room	1983	1.5		
249	647	National	CISF-Factory Main Gate, CISF Control Room	1991	1.5		
250	NN		CISF-Commandant Office,-Visiters Room	1994	1.5		
251	724	Lancer	CISF-Asst. Commandant Office 'J' Gate	1994	1.5		
252	574	Lancer	OHS,"C" Gate, Duty Doctor Room	1987	1.5		

253	126(N)	LG	FMC, Near Works Canteen	2006	1.5		
254	222	National	Carmas Room- LIG (L) Gate	1968	1.5		
255	666	Voltas	Factory Main Gate, Time Office	1991	1.5		
256	658	Avalanche	MIG Gate-Carmas	1994	1.5		
257	729	Avalanche	Carmas Room- 'J' Gate	1996	1.5		
258	307	Voltas	Weigh Bridge,Near 'J' Gate	1974	1.5		
259	779	Avalanche	Scrap Yard, Weighing bridge	1999	1.5		
260	136	Avalanche	Works Canteen Curd Room	1991	1.5		
261	686	Avalanche	Works Canteen Curd Room	1994	1.5		
262	405	Voltas	M&S Stores, Near 06 Block Main Entrance	1982	1.5		
263	158	National	Transport Pool PC Room	1984	1.5		
264	653	Lancer	Boiler House- Laboratory	1991	1.5		
265	74(N)	Lancer	Air Conditioning Section-P.C.Room	1999	1.5		
266	16(N)	LG	Safety Dept.,DGM-G.Narender Rao J-Gate	2004	1.5		
		266 units	SUB- TOTAL IN RUPEES		399.0		
VI	WALK - IN - COOLERS & DEEP FREEGER						
Sl.No	BHEL Cardex Number	MAKE	LOCATION	Year of Purch.	Capacity in TR	Unit rate Rs./TR /year	Total cost per year, Rs.
1	Deep Freezer.-01	Comet Enverons	51 Block Bay 4 Assembly-Sub Zero treatment chm	2006	3.0		
2	W-in-C - 01 to 02	ENCON2x1.4	Wors canteen store	2008	6.0		
3	W-in-C - 03	Eacon 1.5x 2	Staff canteen stores	2008	3.0		
		7 Units	SUB- TOTAL IN RUPEES		12.0		
VII	OIL CHILLRS						
Sl.No	BHEL Cardex Number	MAKE	LOCATION	Year of Purch.		Unit rate Rs./TR /year	Total cost per year, Rs.
1	OC-01	Frigomecca NICA	01Block Bay-2- B-2 - INNSE CNC m/c 1996	1996	5		
2	OC-02	Advanc C.syst	01Block Bay-1 B-2 - INNSE CNC m/c-2006	2006	10		
3	OC-38	EATA	01Block.Bay.2-L-B- 6 -GANARY-2005	2005	2		
4	OC-39	EATA	01Block.Bay.2-L-B- 6 -GANARY-2005	2005	2		
5	OC-40	EATA	01Block.Bay.2-L-B- 6 -GANARY-2005	2005	3		
6	OC-37	EATA	01Block.Bay.1-L-A 6 - Torni Tacchi - 2005	2005	3		
7	OC-04	Advanc C.syst	01 Block Bay-3 C-12 - SKD 50	2004	5		
8	OC-21	Advanc C.syst	01 Block, Bay-3 C-10 & 11 - DORRIES -2004	2004	5		
9	OC-23	George-Holf-Man	01 Block, Bay-3 , C-13 -Mitsubishi MAF 240-1988	1988	2		
10	OC-05	Advanc C.syst	01 Block Bay-4 C-9-Starrage 01-1452 - 2004	2004	5		
11	OC-06	Advanc C.syst	01 Block Bay-4 C-9-Starrage 01-1295 - 2005	2005	5		
12	OC-07	Advanc C.syst	01 Block Bay-4 C-10-Starrage 01-1294 - 2005	2005	5		
13	OC-08	Advanc C.syst	01 Block Bay-4 C-10-Starrage 01-1451 - 2004	2004	5		
14	OC-10	Advanc C.syst	01 Block Bay-4 D-11-BRH-40/A Surface grinding Blade shop -2004	2004	5		
15	OC-34	WARKIN-BKW	01 Block Bay-5 E-8 - KARATS - 1998	1998	2		
16	OC-09	Advanc C.syst	01 Block Bay-5 E-5 - SKODA -SUT 160 - 2000	2000	5		
17	OC-33	SKD-BLANSKO-ESD-71	01 Block Bay-7 G-11 PAL COOPER VCE 1600/140Pal - 1998	1998	5		
18	OC-54	Advanc C.syst	01 Block Bay-7 G-7 - HMT-HMC-630 CNC - 2010	R-134a	2		
19	OC-55	Advanc C.syst	01 Block Bay-7 G-7 - HMT-HMC-630 CNC - 2010	R-134a	2		
20	OC-11	Advanc C.syst	01Block Bay-7, H-5&6-WOTAN Rapi 13 -01-2011 - 2006	2006	5		

21	OC-12	Kelvin	01Block Bay-8 H-6 -ODI Grinding m/c - 2008	2008	3		
22	OC-25	OILMATIC	01 Block, Bay-8, H-9 -O&M	2006	2		
23	OC-20	Chilton	01Block Bay 8 - H-11Praga - Mitsubishi 01-2126 - 2008	2008	5		
24	OC-22	Advanc C.syst	01 Block, Bay-8 H-12 - HMC 1000 - 2002	202	5		
25	OC-24	SCHIMPKE HANN	01 Block, Bay-4,E-8(1622)-Manfort RNC-1002-2000	2000	3		
26	OC-19	SCHIMPKE HANN	01 5 Axis Centre -Strrage ZT 800 - 1994	1994	3		
27	OC-13	SCHIMKE-Kchi	01 5 Axis Centre - SIP - 1994	1994	2		
28	OC-14	MARKSA SA-	01 5 Axis Centre - SIP - 1994	R-22	2		
29	OC-51	Kelvin-CE	01 Block- Buckets & Nozzles -CNC Creep Grinding m/c - 2003	2003	10		
30	OC-52	Kelvin-CE	01 Block- Buckets & Nozzles -CNC Creep Grinding m/c - 2003	2003	10		
31	OC-53	Kelvin-CE	01 Block- Buckets & Nozzles-Horizontal Borring m/c - 2003	203	2		
32	OC-41	Advance c.syst	02Block Bay 3 D-7- SKODA-SUT -160 - 2008	2008	10		
33	OC-26	KELVIN Oil Chiller	02 Block, Bay-2- PAMC CNC - 2002	2002	15.5		
34	OC-42	EATA	02Block.Bay.4-C-2 Caranaghi - Mario - 2004	2004	1.5		
35	OC-43	EATA	02Block.Bay.4-C-2 Caranaghi - Mario - 2004	2004	1.5		
36	OC-44	Pfannenbrg	02Block.Bay.4-B-3 -Juarasti -2006	2006	3		
37	OC-35	Advance c.syst	06 Block Bay 2- HTB III Kolb - 2 - 2008	2008	10		
38	OC-36	Advance c.syst	06 Block Bay 5- Homa lathe m/c - 2008	2008	5		
39	OC-48	Maruthi C.Syst.	06 Block Bay6-Harusler 4 roll bending m/c-2009	2009	10		
40	OC-03	vaghera	06 Block Bay 5- Mout CNC drilling m/c - 2007	2007	3		
41	OC-15	HYPER THERUM	06 Block Bay-3 E-9- plasma cutting - 1986	1986	5		
42	OC-16	Schimpke Hann	51 Block Bay-2 C-12 WHN - 13 CNC	2008	3		
43	OC-31	Advance c. sys	51 Block Bay 3-C10 - Mitshibushi -2004	2004	10		
44	OC-49	Haber oil coole	51 - Block Bay-4 QIER - China - 2008	2008	3		
45	OC-50	Haber oil coole	51 - Block Bay-4 QIER - China - 2008	2008	2		
46	OC-17	Advance c.sys.	70 Block Bay-2 SKS-12 CNC vertical boring m/c	2006	3		
47	OC-18	SCHIMPKE HANN	70 Block Bay-2 - HMC -800	2006	3		
48	OC-45	DASSI	70 Buldg Bay-2-.C-5 -Juaristi	2008	2		
49	OC-46	EATA	70 Buldg Bay-2-D-3-Carnaghi Mario-SPAverti.lathe	2008	2		
50	OC-47	EATA	70 Buldg Bay-2-D-3-Carnaghi Mario-SPAverti.lathe	2008	1.5		
51	OC-27	Advance c.sys.	70 Block Bay-2 - SB CNC-HMT	2006	2		
52	OC-28	Chilton	70 Block Bay-2 - SB CNC-HMT	2006	2		
53	OC-29	Rittal	70 Block Bay-2 - SB CNC-Protate	2007	1		
54	OC-30	Warner Finlay	70 Block Bay-2 - SB CNC-Protate	2007	1		
55	OC-56	Advance c.sys.	06 Block Bay 2- HTB III Kolb - 2 - 2008	2008	10		
56	OC-57	Advance c.sys.	06 Block Bay 2- HTB III Kolb - 2 - 2008	2008	10		
		56 units	SUB- TOTAL IN RUPEES		250.0		
VIII	<u>PANEL AIR CONDITIONERS</u>						
Sl.No	BHEL Cardex Number	MAKE	LOCATION	Year of Purch.	Capacity in TR	Unit rate Rs./TR /year	Total cost per year, Rs.
1	PAC-55	Kelvin	01 Block.Bay2-B2 - INNSE CNC m/c-1996	1996	3		
2	PAC-56	Rittal	01 Block.Bay2 - B5 - Gannery CNC m/c-2004	2004	1		
3	PAC-57	Rittal	01 Block.Bay2 - B5 - Gannery CNC m/c-2004	2004	1		

4	PAC-53	Advance c. sys.	01 Block.Bay2 - B5 - Gannery CNC m/c-2007	2007	1		
5	PAC-54	Advance c. sys.	01 Block.Bay2 - B5 - Gannery CNC m/c-2007	2007	1		
6	PAC-59	Kelvin	01 Block.Bay2- B-6-Torni Tacchi - 2005	2005	1		
7	PAC-60	Kelvin	01 Block.Bay2- B-6-Torni Tacchi - 2005	2005	1		
8	PAC-61	Kelvin	01 Block.Bay2- B-6-Torni Tacchi - 2005	2005	1		
9	PAC-62	Advance c. sys.	01 Block.Bay.3 -C-13 -SKODA - WD 200-2000	2000	1.5		
10	PAC-63	Advance c. sys.	01 Block.Bay.3 -C-13 -SKODA - WD 200-2000	2000	1		
11	PAC-64	Seafest Electruic	01 Block.Bay.3 -C-13 -SKODA - WD 200-1998	1998	1.5		
12	PAC-65	Advance c. sys.	01 Block.Bay.3 -C-13 -SKD - 50-2008	2008	1		
13	PAC-01	Advance c. sys.	01 Block.Bay.3 -C-11 -Dorries-2000	2000	1		
14	PAC-02	Advance c. sys.	01 Block.Bay.3 -C-11 -Dorries-2000	2000	1		
15	PAC-03	Mitsubishi	01 Block.Bay.3 -C-13 -Mitsubishi - MAF 240/180B-1988	1988	1		
16	PAC-04	Freeze Tech	01 Block Bay-3-C--3 - WD - 130A(TOS) - 1998	1998	1		
17	PAC-05	Mitsubishi	01 Block.Bay-4- D 11- HELLER1293	1998	1		
18	PAC-06	Batliboi	01 Block.Bay-4- C 12- Batliboi -2121-Blade shop	1998	1.5		
19	PAC-07	Advance c.sys.	01 Block.Bay-4- C 13- Batliboi -2124-Blade shop	1998	1		
20	PAC-08	Rittal	01 Block.Bay-5- D 13- LB drillingm/c-Blade shop	1998	1		
21	PAC-09	McClean Midwest	01 Block.Bay-5- E 8- KARATS	1996	3		
22	PAC-71	Advance c.sys.	01 Block.Bay-6 -F-4 -Cincinnati Milacron 01-1910 -2008	2008	1		
23	PAC-66	Chilton	01 Block.Bay-6- F-6 - SB-CNC 01-2209 -2000	2000	1		
24	PAC-72	Rittal	01 Block.Bay-6 -F-11-OKK CNC - MCH80001-1623	2000	1		
25	PAC-74	Advance c.sys.	01 Block.Bay-7-G-12 -KirloskarDynacut 250CNC	2002	1		
26	PAC-27	Advance c.sys.	01 Block Bay-7 G-11-PAL CooperVCE1600 VL-2008	2008	1.5		
27	PAC-28	Advance c.sys.	01 Block Bay-7 G-11-PAL CooperVCE1600 VL-2008	2008	1.5		
28	PAC-80	Advance c.sys.	01 Block Bay-7 G-7-HMT-HMC630-2010	2006	1		
29	PAC-75	WarnerFinley	01 Block.Bay-8-H-2 - SKODA-WD 200 - 01-2008	2008	1		
30	PAC-78	Rittal	01 Block.Bay-8-H-3-WD 130-1 - 2007	2007	1		
31	PAC-79	WarnerFinley	01 Block.Bay-8-H-3-WD 130-1 - 2007	2007	1		
32	PAC-76	Rittal	01 Block.Bay-8-H-3-WD 130-2 - 2007	2007	1		
33	PAC-77	Rittal	01 Block.Bay-8-H-3-WD 130-2 - 2007	2007	1		
34	PAC-24	Rittal	01 Block Bay 8 H-5 - Wotan Repi 13-01-2011	2006	1		
35	PAC-105	Rittal	01 Block Bay 8 H- 7 - LODI - Grinding m/c	2008	1.5		
36	PAC-26	Apiste	01 Block Bay 8 H-10 - O&M m/c	2004	1		
37	PAC-73	Advance c.sys.	01 Block.Bay-8 G-11 Max Muller - 2008	2008	1		
38	PAC-69	Rittal	01 BlockBay-8 H-11Praga Mitsubishi 01-2126-2003	2003	1		
39	PAC-93	Advance c.sys.	01 BlockBay-8 H-11 HMC 1000 CNC m/c -2008	2008	1.5		
40	PAC-35	Rittal	01 BlockBay-8 G-12 Manfort RNC-1002- 2000	2000	1		
41	PAC-30	McClean Midwest Canada,	01-5 Axis centre - Strage ZT 800 - 1994	1994	1		
42	PAC-31	McClean Midwest Canada,	01-5 Axis centre - Strage ZT 800 - 1994	1994	1		
43	PAC-32	McClean Midwest Canada,	01-5 Axis centre - Strage ZT 800 - 1994	1994	1		
44	PAC-33	McClean Midwest Canada,	01-5 Axis centre - Strage ZT 800 - 1994	1994	1		
45	PAC-34	McClean Midwest Canada,	01-5 Axis centre - SIP - 2006	2006	1		

46	PAC-81	Pfannenber	01 Block.Bucket & Nozzles-CNC Creep feed grinding m/c 1 - 2003	2003	1		
47	PAC-82	Pfannenber	01 Block.Bucket & Nozzles-CNC Creep feed grinding m/c 2 - 2003	2003	1		
48	PAC-83	Gossijeff	01 Block.Bucket & Nozzles-CNC Horizontal boring m/c - 2003	2003	1		
49	PAC-84	Advance c.sys.	02 Block.Bay-3, C-2&3-SKODA Milling m/c SK125 02-1048 - 2008	2008	1		
50	PAC-90	HIMEL S.A	02 Block.Bay-2, B-2&3 - PAMA CNC - 2002	2002	1		
51	PAC-88	Rittal	02 Block.Bay-3, C-4 -Heller m/c FS-320	2000	1		
52	PAC-92	Advance c.sys.	02 Block.Bay-3, C-4 -Carnaghi Mario - 2004	2004	1		
53	PAC-85	Pfannenber	02 Block.Bay-4, D-4 - Geminis-Goruto CNC-2004	2004	1		
54	PAC-86	Pfannenber	02 Block.Bay-4, D-4 - Geminis-Goruto CNC-2004	2004	1		
55	PAC-98	Rittal	02 Block.Bay-4, C-4 -Juarasti - 2004	2004	1		
56	PAC-29	Advance c.sys.	02 Block Bay 6 G-2 Core slot cutting m/c - 2000	2000	1		
57	PAC-91	Rittal	02 Block Bay 6 G-2 Copper bar sloting m/c - 2008	2008	1		
58	PAC-42	Advance c.sys.	03 Block Bay-2 B-4-STC-25 CNC	2006	1		
59	PAC-43	Advance c.sys.	03 Block Bay-2 B-3-FANUC-10T CNC lathe	2006	1		
60	PAC-44	Advance c.sys.	03 Block Bay-2 B-3-FANUC-10T CNC lathe	2006	1		
61	PAC-94	Rittal	03 Block.Bay-3, E-8-Deckelmaho-DMC-80H m.m/c	2006	1		
62	PAC-89	Advance c. sys.	03 Block Bay-2 - D-6 Vacuume Brazing	2006	1		
63	PAC-17	Rittal	06 Block Bay-5, E-13 Kolb - 1 -2009	2009	1		
64	PAC-18	Rittal	06 Block Bay-5, E-13 Kolb - 1 -2009	2009	1		
65	PAC-19	Rittal	06 Block Bay-5, E-13 Kolb - 1 -2009	2009	1		
66	PAC-20	Rittal	06 Block Bay-5, E-13 Kolb - 1 -2009	2009	1		
67	PAC-21	Rittal	06 Block Bay-5, E-13 Kolb - 1 -2009	2009	1		
68	PAC-22	Rittal	06 Block Bay-5, E-13 Kolb - 1 -2009	2009	1		
69	PAC-23	Rittal	06 Block Bay-5, E-13 Kolb - 1 -2009	2009	1		
70	PAC-99	Advance c. sys.	06 Block.Bay-4, D-13 Kolb - 2 - HTB III -2008	2008	1		
71	PAC-100	Advance c. sys.	06 Block.Bay-4, D-13 Kolb - 2 - HTB III -2008	2008	1		
72	PAC-101	Advance c. sys.	06 Block.Bay-4, D-13 Kolb - 2 - HTB III -2008	2008	1		
73	PAC-102	Advance c. sys.	06 Block.Bay-4, D-13 Kolb - 2 - HTB III -2008	2008	1		
74	PAC-103	Advance c. sys.	06 Block.Bay-4, D-13 Kolb - 2 - HTB III -2008	2008	1		
75	PAC-39	Advance c. sys.	06 Block.Bay-4, D-13 Kolb - 2 - HTB III -2008	2008	1		
76	PAC-37	Advance c. sys.	06 Block.Bay-4, D-13 Kolb - 2 - HTB III -2008	2008	1.5		
77	PAC-38	Advance c. sys.	06 Block Bay-5 E-10 - Batliboi - BR-6-1	1998	1		
78	PAC-51	Kelvin	06 Block Bay-5 E-3 -Mount CNC drilling m/c-2007	2007	1.5		
79	PAC-52	Kelvin	06 Block Bay-5 E-3 -Mount CNC drilling m/c-2007	2007	1.5		
80	PAC-95	Sun Beam	51 Block Bay-2 C-12 - WHN-13 CNC m/c	2008	1		
81	PAC-40	Sun Beam	51 Block Bay-2 D-10 - Cooper Cvt-150.2-CNC4000	2008	1.5		
82	PAC-41	Advance c. sys.	51 Block Bay-2 D-10 - Cooper Cvt-150.2-CNC4000	2008	1		
83	PAC-87	Rittal	51 Block Bay-1 E-7 - Gloria-Italy CNC - 2005	2005	1		
84	PAC-96	Rittal	51 Block Bay-1 E-7 - Gloria-Italy CNC - 2005	2005	1		
85	PAC-16	Advance c. sys.	51 block Bay - 1 D-12 - HMT - L45	2002	1		
86	PAC-58	Advance c. sys.	51 Block Bay-3 - B1-SKODA drilling m/c WD-200-2009	2009	1		
87	PAC-68	Advance c. sys.	51 Block Bay-3 - B1-SKODA drilling m/c WD-200-2009	2009	1		
88	PAC-13	Haber Pasion Instr.	51 - Block Bay-4 -E11-QIER - China - 2008	2008	1		

89	PAC-14	Haber Pasion Instr.	51 - Block Bay-4 -E11-QIER - China - 2008	2008	1		
90	PAC-107	Japan make NN	51 - Block Bay-4 -E11-TMD-60/70 - japan - 2008	2008	1		
91	PAC-25	Rittal	51- Block Bay-4 -Wailer CNC Travel Drill.m/c- 2007	2007	1		
92	PAC-45	WarnerFinley	70 Bldg. Bay-2 HMT- L45 CNC lathe	2004	1		
93	PAC-46	Advance c. sys.	70 Bldg. Bay-2 - WHN 13.8 CNC	2006	1		
94	PAC-47	Rittal	70 Bldg. Bay-2 - SKS-12 CNC Vertical boring m/c	2006	1		
95	PAC-48	Rittal	71 Bldg. Bay-2-SKS-12 CNC Vertical boring m/c	2006	1		
96	PAC-49	Advance c. sys.	70 Bldg. Bay-2 - HMC 800 CNC m/c	2006	1		
97	PAC-50	Advance c. sys.	70 Bldg. Bay-2 - HMC 800 CNC m/c	2006	1		
98	PAC-12	Advance c. sys.	70 Bldg. Bay-2 - SB CNC Protatt PL850U	2006	1		
99	PAC-104	Rittal	70 Bldg. Bay-2 - D3 Caranagi Mario -2006	2006	1		
100	PAC-106	Rittal	70 Bldg. Bay-2 - C5 Juaristi	2006	1		
101	PAC-36	Advance c. sys.	Boiler Hoyse 20 TR Control panel -2006	2006	1.0		
		101 Units			110.5		
IX PENDING COOLERS							
Sl.No	BHEL Cardex Number	MAKE	LOCATION	Year of Purch.	Capacity in TR	Unit rate Rs./TR /year	Total cost per year, Rs.
1	PND-01	Batliboi	01 Block.Bay-4 - C-11-Batliboi SW-68 Bld. Shop	R134a	0.5		
2	PND-02	Pendant AC	01 Block.Bay-4 - C-11-Heller -1293	R134a	0.5		
3	PND-03	Batliboi	01 Block.Bay-4 - C-12-Batliboi - 2114 Bld. Shop	R134a	0.5		
4	PND-04	Rittal	01 Block.Bay-6-F11-OKK CNC-MCH80001-1623	R134a	0.5		
5	PND-05	Rittal	01 Block Bay 8 H- 5 - Wotan Repi 13-01-2011	R134a	0.5		
6	PND-06	Rittal	01 Block Bay 8 H- 7 - LODI - Grinding m/c - 2008	R134a	1.5		
7	PND-07	Rittal	01 BlockBay-8 G-12 Manfort RNC-1002- 2000	R134a	0.5		
8	PND-08	Rittal	02 Block.Bay-3, C-4 -Carnaghi Mario - 2004	R134a	1		
9	PND-09	Rittal	02 Block.Bay-4, C-4 -Juarasti - 2004	R134a	0.5		
10	PND-10	Godrej	06 Block Bay-5, E-13 Kolb - 1 -2009	R22	1		
11	PND-12	Hyperthermo	06 Block.Bay-1, A-5 - Plasma cutting - 2006	R134a	0.5		
12	PND-13	Rittal	06 Block.Bay-1, A-2 - Messer-Pioled CNC cutting m/c	R134a	0.5		
13	PND-14	Rittal	51 Block Bay-1 E-7 - Gloria-Italy CNC - 2005	R134a	0.5		
14	PND-16	Advance c. sys.	51 block Bay - 1 D-12 - HMT - L45	R22	1		
15	PND-17	Advance c. sys.	51 Block Bay-2 - C10-VDF Lathe m/c -2006	R134a	0.5		
16	PND-18	Haber Pasion Instr.	51 - Block Bay-4 -E11-QIER - China - 2008	R-134a	0.5		
17	PND-19	Advance c. sys.	70 Bldg. Bay-2 - SB CNC Protatt - PL850U	R134a	0.5		
18	PND-20	Rittal	70 Bldg. Bay-2-D3- Carnagi MarioCNC	R134a	0.5		
		18 units	SUB- TOTAL IN RUPEES		11.5		
X AIR DRIERS							
Sl.No	BHEL Cardex Number	MAKE	LOCATION	Year of Purch.	Capacity in TR	Unit rate Rs./TR /year	Total cost per year, Rs.
1	AD-03	GEM-Air Driver	01 Block.Bay1- A-6- Torni Tacchi	407c	1		
2	AD-04	ELGI-Air Drier	01 Block.Bay8- H-5 Wotan Rapol	407c	1		
3	AD-05	GEM-Air Driver	01 Block Bay8 - Lodi drandig m/c-2008	407c	1		
4	AD-06	Summit	01 Block.Bucket & Nozzles horiz. Machine -2003	R134a	1		

5	AD-07	SANPAR	01 Block.Bucket & Nozzles 3 D measurig m/c-2003	R134a	1		
6	AD-08	Air Drier-GEM	02 Block.Bay-3, C-2&3 Caranagi Mario - 2004	R134a	1		
7	AD-09	SANPAR	02 Block.Bay-1, B-2	R134a	1		
8	AD-10	SANPAR	02 Block.Bay-6 Slot cutting m/c	R134a	1		
9	AD-11	IDFA6E	02 Block.Bay-7 - Copper bars slot cutting m/c	R134a	1		
10	AD-12	SANPAR	03 Block.Bay-3, E-8- Funac CNC m/c	R407C	1		
11	AD-13	ELGI	51 Bcock Bay1 - E7- Gloria CNC m/c	R407C	1		
12	AD-14	ELGI	51 Bcock Bay4 - TMD - 60/70 CNC m/c	R407C	1		
13	AD-15	GEM	70 Block, Bay-2, D-3 - Caranagi Mario	R134a	1		
14	AD-16	GEM	70 Block, Bay-2, C-5 - Juarisiti	R134a	1		
15	AD-17	GEM	70 Block, Bay-2, C-5 - Juarisiti	R134a	1		
		15 Units	SUB- TOTAL IN RUPEES		15.0		

XI

Sl.No	BHEL Cardex Number	MAKE	LOCATION	Year of Purch.	Capacity in TR	Unit rate Rs./TR /year	Total cost per year, Rs.
1	General Hospital O.P.D. Evaporative cooling system	U.E.C.	General Hospital Male, female wards O.P.D. Evaporative cooling system	2009	5 X 10 K.W.		
		5 units	SUB- TOTAL IN RUPEES		5 nos.		

XII REFRIGERATORS

Sl.No	BHEL Cardex Number	MAKE	LOCATION	Year of Purch.	Capacity in TR	Rate per year, Rs.
1	R-01 (N)	LG	Godavari Guest House, Kitchen room	2004	280.0	
2	R-02 (N)	LG	Godavari Guest House, Dining Hall	2004	280.0	
3	R-03 (N)	LG	ED,s Residence	2004	280.0	
4	R-04 (N)	LG	Gen.Hospital, Kitchen Room	2005	175.0	
5	R-05 (N)	LG	Gen.Hospital, immunization, OPD, 1 st Fl.	2005	175.0	
6	R-06 (N)	LG	Gen.Hospital, AMC Ward	2005	175.0	
7	R-07 (N)	LG	Gen.Hospital, Male Surgical Ward	2005	175.0	
8	R-08 (N)	LG	Gen.Hospital, Maternity Ward	2005	175.0	
9	R-09 (N)	LG	Guest House, SHOOT LEFT	2005	175.0	
10	R-10 (N)	LG	Guest House, Room No- 106	2005	175.0	
11	R-11 (N)	LG	Guest House, Room No- 108	2005	175.0	
12	R-12 (N)	LG	01 Annexe, 1st Fl., Sr.DGM- K.Rajeswara Rao/can be taken back	2005	175.0	
13	R-13 (N)	LG	Godavari Guest House, Room No-208	2005	175.0	
14	R-14 (N)	LG	Godavari Guest House, Room No-210	2005	175.0	
15	R-15 (N)	LG	Godavari Guest House, Room No-207	2005	175.0	
16	R-16 (N)	LG	EDP Bldg. conference hall/HAS TO BE COLLECTED	2005	175.0	
17	R-17 (N)	LG	Godavari Guest House, Room No-205	2005	175.0	
18	R-18 (N)	LG	Adm.Bld., 1st Fl., AGM- N.N.DAWN/Fin	2006	175.0	
19	R-19 (N)	LG	EDP BLDG, AGM-P.Narayana Rao,	2006	175.0	
20	R-20 (N)	LG	02 Annex, Gr. Fl., AGM- ravindra nath babu	2006	175.0	
21	R-21 (N)	LG	Adm.Bld,2nd Fl, GM- Mr.Vijaya Rao(SG/M&S)	2006	175.0	
22	R-22 (N)	LG	Factory civil,Sr.DGM-A.Krishna Rao	2006	175.0	
23	R-23 (N)	LG	HRDC-AGM-B.SANKARAI AH	2006	175.0	
24	R-24 (N)	LG	Adm.Bld 2nd Fl,AGM-G.Appana Sastry	2006	175.0	
25	R-25 (N)	LG	Adm.Bld., 1st Fl.GM-S.K.Jain	2006	175.0	
26	R-26 (N)	LG	Adm.Bld., 1st Fl.GM-R.K.Wanchoo	2006	175.0	

27	R-27 (N)	LG	Safety Engg. Dept., Mr.J.N.Rao,AGM (Purchased thro their own dept.)	2006	175.0		
28	R-28 (N)	VIDEOCON	AdmBldg,3rd Fl., AGM- H.S.Kalsi	2006	180.0		
29	R-29 (N)	VIDEOCON	AdmBldg,3rd Fl., AGM- CH.N.V.Murthy	2006	180.0		
30	R-30 (N)	VIDEOCON	Gen.Hosp.-AGM -Dr.D.Nagesh	2006	180.0		
31	R-31 (N)	VIDEOCON	Admn. Bldg., Gr.Fl., I.R.Department-DGM-S.Vargees	2006	180.0		
32	R-32 (N)	VIDEOCON	New Engg.Building, AGM- B.I.BABU	2006	180.0		
33	R-33 (N)	VIDEOCON	Admin 2nd Flr., AGM- K.Maisaiah	2006	180.0		
34	R-34 (N)	LG	Gen.Hospital Medical Stores	2006	300.0		
35	R-35 (N)	VIDEOCON	07 Annex, 1st. Fl.-AGM N.S.Rao	2007	180.0		
36	R-36 (N)	VIDEOCON	01 Annexe 1st Flr, AGM-T.M.RAO, .	2007	180.0		
37	R-37 (N)	VIDEOCON	02 Annexe , 1st.Fl., AGM-Ashok Varma,	2007	180.0		
38	R-38 (N)	VIDEOCON	Godavari Guest House, Room No-217	2007	180.0		
39	R-39 (N)	VIDEOCON	Godavari Guest House, Room No-218	2007	180.0		
40	R-40 (N)	VIDEOCON	Godavari Guest House, Room No-111	2007	180.0		
41	R-41 (N)	VIDEOCON	Godavari Guest House, Room No-112	2007	180.0		
42	R-42 (N)	VIDEOCON	Admn.Bldg., Gr.Fl,GM-A.Victor ,	2007	180.0		
43	R-43 (N)	VIDEOCON	Factory civil,conference hall/P.J.REDDY	2007	180.0		
44	R-44 (N)	VIDEOCON	AGM- Bala Ram Murthy, 06 BLOCK.	2007	180.0		
45	R-45 (N)	VIDEOCON	01 Annex, Gr. Fl., AGM-K.V.P.Rao	2007	180.0		
46	R-46 (N)	VIDEOCON	03 Block, Sr.DGM-Ravindranadh	2007	180.0		
47	R-47 (N)	VIDEOCON	Admn.Bldg., 2nd Fl,GM-D.Ashok, .	2007	180.0		
48	R-48 (N)	VIDEOCON	Engg.Bldg., 1st Fl,AGM-Sandeep Narang,	2007	180.0		
49	R-49 (N)	VIDEOCON	51 Block AGM, mR.BASU	2007	180.0		
50	R-50 (N)	VIDEOCON	OHS (Occupational Health Centre), 'C' gate, Injection Room	2007	180.0		
51	R-51(N)	VIDEOCON	07 Annexe,1st Fl,GM-G.Rama Mohan Rao, .	2007	180.0		
52	R-52(N)	VIDEOCON	01 Annexe,Gr. Fl.- Ex-GM-y.konda reddy	2007	180.0		
53	R-78(N)	SAMSUNG	86 Bldg,1st.fl.AGM Gadghave	2009	190.0		
54	R-79(N)	SAMSUNG	01 Annex, 1st Fl, AGM- A.B.Ravi chander	2009	190.0		
55	R-80(N)	SAMSUNG	01 Annex, 1st Fl, AGM-G.Uday Kumar	2009	190.0		
56	R-81(N)	SAMSUNG	70 Building, AGM-AMV Yugandhar	2009	190.0		
57	R-82(N)	SAMSUNG	51 Block, AGM- T.Nageswara Rao	2009	190.0		
58	R-83(N)	SAMSUNG	06 ANNEXE 1st floor, AGM-S.Pallam Raju	2009	190.0		
59	R-84(N)	SAMSUNG	06 ANNEXE 1st floor,AGM-T.Anand Rao	2009	190.0		
60	R-85(N)	SAMSUNG	Admn.Bldg., 1st.Fl. AGM-S.Panchadar	2009	190.0		
61	R-86(N)	SAMSUNG	Admn.Bldg., 4th Fl. AGM-G.S.Ashok kumar	2009	190.0		
62	R-87(N)	SAMSUNG	03 Annex,Gr.Fl-AGM-K.V.Sharma	2009	190.0		
63	R-88(N)	SAMSUNG	02 Annexe Gr.Flr-AGM-K.Sudarsan Rao	2009	190.0		
64	R-89(N)	SAMSUNG	02 Annex,Gr.Fl-AGM-R.Acharya	2009	190.0		
65	R-90(N)	SAMSUNG	06 Annex,Gr.Fl-Micro Printing Room	2009	190.0		
66	R-91(N)	SAMSUNG	02 Annex,1st.Fl-AGM-U.Sridhar	2009	190.0		
67	R-92(N)	SAMSUNG	06 Annex, 1st Fl, AGM-A.K.Kalluraya	2009	190.0		
68	R-93(N)	SAMSUNG	TIC Bldg-AGM.KULKARNI	2009	190.0		
69	R-94(N)	SAMSUNG	OHS (Occupational Health Centre), 'C' gate,	2009	190.0		
70	R-95(N)	SAMSUNG	29 Building, Chemical Lab	2009	190.0		
71	R-96(N)	SAMSUNG	29 Building,Gr.Fl. AGM-P.V.Ramulu	2009	190.0		
72	R-97(N)	SAMSUNG	Factory Medical Centre, Near Works Canteen	2009	190.0		
73	R-98(N)	SAMSUNG	Asst.Commandant Office, "J" Gate	2009	190.0		
74	R-99(N)	SAMSUNG	36/11, Annex, 1st Fl. AGM/CDC, SG-B.K.NAIR	2009	190.0		
75	R-100(N)	SAMSUNG	02 Annex,Gr.Fl-AGM-Lakshmi Kantha Rao	2009	190.0		
76	R-101(N)	SAMSUNG	90 Building, Electrical Lab	2009	190.0		
77	R-102(N)	SAMSUNG	90 Building, Instrumentation	2009	190.0		

78	R-103(N)	SAMSUNG	90 Building, Q.C. Calibrating Lab	2009	190.0		
79	R-104(N)	SAMSUNG	06 Block, N.D.T	2009	190.0		
80	R-105(N)	SAMSUNG	06 Block, Welding Engg.	2009	190.0		
81	R-106(N)	SAMSUNG	CISF, ORS Mess, BHEL T/S	2009	190.0		
82	R-107(N)	SAMSUNG	ORS MESS	2009	190.0		
83	R-108(N)	SAMSUNG	51 Canteen	2009	190.0		
84	R-109(N)	SAMSUNG	staff Canteen-Umesh chandran	2009	190.0		
85	R-110(N)	SAMSUNG	Admn.Bldg., 1st.Fl. GM-sri Vastava	2009	190.0		
86	R-111(N)	SAMSUNG	01 Block AGM-S.Bhaskar Rao	2009	190.0		
87	R-112(N)	SAMSUNG	Estate Office,T/S, AGM-T.K.Sailash	2009	190.0		
88	R-113(N)	SAMSUNG	adm.1st flr,Finance, AGM- AVM RAO	2009	190.0		
89	R-114(N)	SAMSUNG	01 Annexe 1st Flr, AGM-Madan mohan	2009	190.0		
90	R-115(N)	SAMSUNG	New Engg.Bldg.,2nd Fl-AGM-CNV.Ramana	2009	190.0		
91	R-116(N)	SAMSUNG	General Hospital Dr.PP. Sharma	2009	190.0		
92	R-117(N)	SAMSUNG	02 Annex,Gr.Fl-AGM-C.Suresh Kumar	2009	190.0		
93	R-118(N)	SAMSUNG	A.P.Ashok CAN BE TAKEN BACK/Adm.1st flr	2009	190.0		
94	R-119(N)	SAMSUNG	Admn.Bldg., 3rd Fl. AGM-K.S.Subramanyam	2009	190.0		
95	R-120(N)	SAMSUNG	Admn.Bldg.4th flt.AGM, Anil Ranade	2009	190.0		
96	R-121(N)	SAMSUNG	04 Annex, Gr.Fl., AGM-P.Satyanarayana	2009	190.0		
97	R-122(N)	SAMSUNG	Boiler House Lab	2009	190.0		
98	R-123(N)	SAMSUNG	Admn.Bldg., 1st.Fl. GM-K.Nivedan	2009	190.0		
99	R-124(N)	SAMSUNG	New Engg.Bldg.- 2nd Fl- AGM-P.Nageswara Rao	2009	190.0		
100	R-125(N)	SAMSUNG	Admn.Bldg., 2nd.Fl. GM-Aravind Gupta	2009	190.0		
101	R-126(N)	SAMSUNG	Admn.Bldg., 2nd.Fl. AGM-Ram Kuchel	2009	190.0		
102	R-127(N)	SAMSUNG	02 Annexe, 1st Fl.-AGM-M.Vijaya Kumar	2009	190.0		
103	R-128(N)	SAMSUNG	Admn.Bldg., 2nd.Fl. AGM-Siva Narayana,Room-221	2009	190.0		
104	R-129(N)	SAMSUNG	36/11, Annex, 2nd Fl. AGM-C.V.Shambu Prasad	2009	190.0		
105	R-130(N)	SAMSUNG	International Club, BHEL T/S	2009	190.0		
106	R-131(N)	SAMSUNG	International Club, BHEL T/S	2009	190.0		
107	R-132(N)	SAMSUNG	Godavari Guest House, Room-201	2009	190.0		
108	R-133(N)	SAMSUNG	Godavari Guest House, Room-202	2009	190.0		
109	R-134(N)	SAMSUNG	HRDC Ladies Hostel, BHEL T/S	2009	190.0		
110	R-135(N)	SAMSUNG	07 Annex, 2nd.Fl, AGM-C.S.R.Murthy	2009	190.0		
111	R-136(N)	SAMSUNG	Gen.Hospital, Medical Stores, Tablet Section	2009	190.0		
112	R-137(N)	SAMSUNG	Gen.Hospital, Medical Stores, Syrup Section	2009	190.0		
113	R-138(N)	SAMSUNG	General Hospital, Lab, Room-11	2009	190.0		
114	R-139(N)	SAMSUNG	General Hospital, Lab, Room-7	2009	190.0		
115	R-140(N)	SAMSUNG	General Hospital, Lab Stores	2009	190.0		
116	R-141(N)	SAMSUNG	General Hospital, Female Ward	2009	190.0		
117	R-142(N)	SAMSUNG	General Hospital, Male Ward	2009	190.0		
118	R-143(N)	SAMSUNG	General Hospital, Kitchen Room	2009	190.0		
119	R-144(N)	SAMSUNG	General Hospital, ENT Dept.	2009	190.0		
120	R-145(N)	SAMSUNG	General Hospital, Female Surgical Ward	2009	190.0		
121	R-146(N)	SAMSUNG	General Hospital, Operation Theatre	2009	190.0		
122	R-147(N)	SAMSUNG	02 Annex,2nd.Fl- FSS AGM-C.L.Kayakar	2009	190.0		
123	R-148(N)	SAMSUNG	02 Annex,2nd.Fl- FSS AGM-D.Chandra Sekhar Rao	2009	190.0		
124	R-149(N)	SAMSUNG	HRDC OFFICE ROOM	2009	190.0		
125	R-150(N)	SAMSUNG	General Hospital, Lab, Room-18	2009	190.0		
126	R-151(N)	SAMSUNG	Godavari Guest House, Adarsh Dining Hall	2009	190.0		
127	R-152(N)	SAMSUNG	Admn.Bldg., 4th.Fl. AGM-M.N.Koteswara Rao	2009	190.0		

128	R-153(N)	SAMSUNG	New Engg.Bldg, 2nd Fl., AGM-K.Ramachandra Rao	2009	190.0		
129	R-154(N)	SAMSUNG	Admn.Bldg., 2nd.FI. AGM-K.E.P.C. Kumar, Room-215	2009	190.0		
130	R-155(N)	SAMSUNG	Admn.Bldg., Gr.FI. HR AGM-Phaninder Kumar	2009	190.0		
131	R-156(N)	SAMSUNG	Admn.Bldg., 2nd.FI. AGM-R.N.DAS	2009	190.0		
132	R-157(N)	SAMSUNG	02 Annex,2nd.FI- AGM-a.p.c.Rao	2009	190.0		
133	R-158(N)	SAMSUNG	51 Annex, 1st FI.AGM-M.D.Prasanna Kumar	2009	190.0		
134	R-159(N)	SAMSUNG	General Hospital, ENT Dept.	2009	190.0		
135	R-160(N)	SAMSUNG	General Hospital, Sp.Ward Staff Room	2009	190.0		
136	R-161(N)	SAMSUNG	Admn.Bldg., Gr.FI. HR AGM-K.Adishesu	2009	190.0		
137	R-162(N)	SAMSUNG	70 Building, AGM-P.Bapu Reddy	2009	190.0		
138	R-163(N)	SAMSUNG	70 Build., AGM- yughandar	2009	190.0		
139	R-164(N)	SAMSUNG	Admn.Bldg. 1st.Floor, Vigelance Dept.	2009	190.0		
140	R-165(N)	SAMSUNG	Tel.Exchange-AGM-S.A.Srikanth	2009	190.0		
141	R-166(N)	SAMSUNG	Admn.Bldg. 2nd Fl., AGM-B.D.Pandey	2009	190.0		
142	R-167(N)	SAMSUNG	Ladies Welfare Centre	2009	190.0		
143	R-168(N)	SAMSUNG	Admn.Bldg., 1st Fl. P&D AGM-P.Badri narayana rao	2009	190.0		
		143 units	SUB- TOTAL IN RUPEES				

Total 1873 TR Capacity of Ref & AC equipment in BHEL, 5 Evaporative cooling **1873.0** Rs.

TOTAL FOR 143 NOS REFREGERATORS

Rs

GRAND TOTAL IN RUPEES

TAXES IF ANY: